



Figure 1

SITUATION de L'ETUDE

GESPUNSART - Puits de «La Lutinière»

00692X0009
00692X0062
BSS003QUNY
BSS003QUQG
BSS003QUQA
BSS003QUQK
BSS003QURU
BSS003QUQO



* Puits 00692X0062
• Piézomètres